



Type	Change	Vehicle / Model
Jaguar		Download Ref : JAG46
Improvement	Resolved issue with fault clear on ABS module	S-Type X204 (2004)
Improvement	Resolved issue with fault clear on ACC/SBC module	XK8/XKR X100 (2004)
Improvement	Resolved issue with RCM module faults in Quick test	X-Type X400
Land Rover		Download Ref : LR64
Improvement	Function to Add Additional Keys updated	Discovery L319 (2010)
Improvement	Function to Add Additional Keys updated	Discovery L319 (2012)
Improvement	Function to Add Additional Keys updated	Range Rover L322 (2010)
Improvement	Function to Add Additional Keys updated	Range Rover Sport L320 (2010)
Improvement	Function to Add Additional Keys updated	Range Rover Sport L320 (2012)
Improvement	Improvements made to IPC Module Programming	Range Rover L322 (2010)
Improvement	Side step service mode updated	Range Rover L405
Improvement	Side step service mode updated	Range Rover Sport L494
Mercedes		Download Ref : MERC155
Improvement	Camshaft actual values and actuations updated	C-Class 204
Improvement	DISTRONIC coding in Central Gateway CGW updated	E-Class 211
Improvement	Communication to the Top Module RVC improved	SL 230
Improvement	Ignition switch EIS initial startup procedure improved	Vito 639
Improvement	Instrument Cluster Coding of the Fuel Tank Option updated	E-Class 211
Improvement	Instrument Cluster Initial Start Up process improved	S-Class 221
PSA		Download Ref : PSA52
Improvement	Additive diagnostic pages standardised	Peugeot 207
Improvement	Quick test report now can be refreshed after ECU variant has been chosen	ALL
Improvement	Quick test reports updated to make choosing a control unit variant more clear	ALL
Renault		Download Ref : RENAULT51
Improvement	DPF regeneration function improved for Engine variant INJ_EDC16C3_VDIAG5C_C1	Megane 2
Improvement	DPF regeneration function improved for Engine variant INJ_EDC16C36_VDIAG4X_0A	Megan 3
Improvement	DPF regeneration function improved for Engine variant INJ_EDC17C42_VDIAGC1_05	Megan 3
Improvement	DPF regeneration function improved for Engine variant INJ_EDC17CP19_VDIAG44_95	Megan 3
Improvement	DPF regeneration function improved for Engine variant INJ_SID307_VDIAGXX_FX	Megan 3
Improvement	DPF regeneration function improved for Engine variant INJ_EDC16C3_VDIAG50_C1	Megane 2
Improvement	DPF regeneration function improved for Engine variant INJ_EDC16C36_VDIAG4X_91	Megane 2
Improvement	DPF regeneration function improved for Engine variant INJ_EDC16C36_VDIAG5X_91	Megane 2
Improvement	DPF regeneration function improved for Engine variant INJ_EDC16CP33_VDIAG2X_C4	Megane 2
Improvement	DPF regeneration function improved for Engine variant INJ_EDC16CP33_VDIAGXX_C4_v2	Megane 2
Improvement	Handling of communications improved for DPF regeneration function in Engine variant (INJ_SID307_VDIAGXX_FX)	Megan 3
VAG		Download Ref : VAG90
Enhancement	Service interval coding added	VW UP
Improvement	Service reset function improved	VW UP
Improvement	When performing a security function the pin code will be displayed on the screen for backup reference	Models with Immobiliser 1,2 or 3
Improvement	When selecting the Parking brake control unit a message will advise to save the coding of the ABS control unit before doing any work on the parking brake.	Passat 3c
Volvo		Download Ref : MAIN443
Improvement	Quick test updated to stop logging error message from appearing	S60 (2011)